

INCOMING INSPECTION REPORT


Demonstration document with sample data — not an aircraft maintenance record.

PART NUMBER	SERIAL NUMBER
8063-217	DEMO-1187
DESCRIPTION	SALES ORDER
FUEL CONTROL ASSY	SO-2214
CONDITION	QUANTITY
Serviceable (SV)	1 EA
RECEIVED	INSPECTOR
July 31, 2026	S. Barbour — Stamp #01


INSPECTION CHECKLIST

- ☒ No shipping damage observed; packaging satisfactory
- ☒ Data plate legible and matches paperwork
- ☒ Protective caps and plugs installed on all ports
- ☒ Trace documentation present and consistent

CONDITION PHOTOS (AVPICS)



IMG_SO-2214_PN8063217_001.jpg



IMG_SO-2214_PN8063217_002.jpg

Electronically signed and sealed via AvTools Sign & Seal. Sample document sealed with a demonstration certificate; production seals chain to the company signing certificate and are publicly verifiable.